10

16

14

12

18

PRIOR
ART

Figure #1

Figure #2

Figure 3

Figure 4

Figure #5

12 ―

― 20

18 ―

― 42

Figure #6

Figure #7

Figure #8A

Process Area for heat setting

Process Area for Cool down

Figure #9A

Figure #8B

Figure #9B

Figure #9D

Figure #10C

Figure #9C

Figure #10A

Figure #10B

Figure #10D

Figure #11

Figure #12